



Our Ref : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-01/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	141.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Inside Building (1)								
JT - 39	10	3	141.3	7	0 - 1	Inc	Reject	
					1 - 2	Por	Reject	
					2 - 0	Por / LF	Reject	

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II
 Interpreted & Evaluated By: Amat Hamidi - NDT Lev.II
 Date: 17 April 2018



Client Representative:
 Name:
 Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-02/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	141.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Inside Building (1)								
JT - 40	10	3	141.3	7	0 - 1	Por	Accept	
					1 - 2	Por	Reject	
					2 - 0	Por	Accept	

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II

Interpreted & Evaluated By: Amat Hamidi - NDT Lev. II

Date: 17 April 2018



Client Representative:

Name:
Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-03/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Flyover								
JT - 239	10	3	114.3	7	0 - 1	NRI	Accept	
					1 - 2	NRI	Accept	
					2 - 0	NRI	Accept	

_____ End of Report _____

Legend:

Ti : Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II

Interpreted & Evaluated By: Amat Hamidi - NDT Lev.II

Date: 17 April 2018



Client Representative:

Name:

Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1

Report No: I NDT/RT/180412-04/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Flyover								
JT - 243	10	3	114.3	7	0 - 1 1 - 2 2 - 0	NRI Inc No Film	Accept Reject	 Reshoot

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II

Interpreted & Evaluated By: Amat Hamidi - NDT Lev. II

Date: 17 April 2018



Client Representative:

Name:

Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1

Report No: I NDT/RT/180412-05/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT	RT	Pipe Diameter	Material Thickness	Film Position	Film Interpretation	Result	Remarks
	(mm)	(mm)	(mm)	(mm)				
Flyover								
JT - 241	10	3	114.3	7	0 - 1	Por	Accept	
					1 - 2	NRI	Accept	
					2 - 0	LF	Reject	

_____ End of Report _____

Legend:

TI : Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II

Interpreted & Evaluated By: Amat Hamidi - NDT Lev. II

Date: 17 April 2018



Client Representative:

Name:

Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-06/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Flyover								
JT - 242	10	3	114.3	7	0 - 1	NRI	Accept	
					1 - 2	NRI	Accept	
					2 - 0	Por	Reject	

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II
 Interpreted & Evaluated By: Amat Hamidi - NDT Lev. II
 Date: 17 April 2018



Client Representative:
 Name:
 Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-07/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Flyover								
JT - 240	10	3	114.3	7	0 - 1	LF		Reject
					1 - 2	Por		Accept
					2 - 0	Con		Accept

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II
 Interpreted & Evaluated By: Amat Hamidi - NDT Lev.II
 Date: 17 April 2018



Client Representative:
 Name:
 Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1
 Report No: I NDT/RT/180412-08/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client : Recron (M) Sdn Bhd	Procedure No: NT/RT/ASME Rev. 7.0
Project : HTM Piping	IQI type : ASTM 1B
Material: Carbon Steel	Film Manufacturer/Type : FUJI 100(class II)
Welding Process : GTAW	Density : 2.0 - 3.5
Examination Code : ASME V	Sensitivity: 0.33mm(5 wires visible)
Acceptance Code: ASME B31.3	Source to Object Distance : 114.3mm
Examination Date: 16 April 2018	Source Side of Object to Film Distance: (7+3)mm
	No of Radiograph(exposure) : Single Exposure
	No. of Film Each Cassette : 1 Film
	Radiographic Technique : DWSI
	Film Viewing Technique : Single Viewing
	Source Type/Size : Iridium192 (3.2mm)
	Location Markers : Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT (mm)	RT (mm)	Pipe Diameter (mm)	Material Thickness (mm)	Film Position	Film Interpretation	Result	Remarks
Flyover								
JT - 238	10	3	114.3	7	0 - 1 1 - 2 2 - 0	Por LF NRI	Accept Reject Accept	

_____ End of Report _____

Legend:

TI : Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI : Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II
 Interpreted & Evaluated By: Amat Hamidi - NDT Lev.II
 Date: 17 April 2018



Client Representative:
 Name:
 Date:



Our Ref. : NT/103528/18-09

Page No: 1 of 1

Report No: I NDT/RT/180412-09/18

RADIOGRAPHIC EXAMINATION REPORT

Client and Testing Particulars

Client :	Recron (M) Sdn Bhd	Procedure No:	NT/RT/ASME Rev. 7.0
Project :	HTM Piping	IQI type :	ASTM 1B
Material:	Carbon Steel	Film Manufacturer/Type :	FUJI 100(class II)
Welding Process :	GTAW	Density :	2.0 - 3.5
Examination Code :	ASME V	Sensitivity:	0.33mm(5 wires visible)
Acceptance Code:	ASME B31.3	Source to Object Distance :	114.3mm
Examination Date:	16 April 2018	Source Side of Object to Film Distance:	(7+3)mm
		No of Radiograph(exposure) :	Single Exposure
		No. of Film Each Cassette :	1 Film
		Radiographic Technique :	DWSI
		Film Viewing Technique :	Single Viewing
		Source Type/Size :	Iridium192 (3.2mm)
		Location Markers :	Film Side

Radiographic Examination Result

Weld Reference (Welder No)	WT	RT	Pipe Diameter	Material Thickness	Film Position	Film Interpretation	Result	Remarks
	(mm)	(mm)	(mm)	(mm)				
Flyover								
JT - 69 R1	10	3	114.3	7	1-2	LF	Reject	

_____ End of Report _____

Legend:

TI: Tungsten Inclusion	NRI: No Relevant Indication	Uc: Undercut	Por: Porosity	WT: Weld Thickness
SI: Slag Inclusion	LP: Lack of Penetration	Con: Concavity	BT: Burn Through	RT: Reinforcement Thickness
LF: Lack of Fusion	EP: Excess Penetration	AR: Artifact	Sur: Surface	

Personnel Particulars

Radiographer : Emirsham - NDT Lev. II

Interpreted & Evaluated By: Amat Hamidi - NDT Lev. II

Date: 17 April 2018



Client Representative:

Name:
Date: